

LiteShow II 2.10 Patch Installer Release Notes  
Copyright © 2007-2008 InFocus Corp. All rights reserved.  
June 2008

=====  
Issues resolved in this patch

=====  
This patch installer for LiteShow Manager 2.10 resolves several issues found after the product release. This patch will not work on earlier versions of LiteShow Manager.

After installing LiteShow Manager 2.10 client, execute the file LSPatch.exe.

The 2.10 LiteShow II Adapter firmware and LiteShow Manager client can be located at:

<http://www.infocus.com/support/liteshowII>

(select the Documents Tab, then scroll to the Downloads section).

**\* Compatibilty with other products that use a Mirror Driver:**

This patch resolves an issue where LiteShow Manager could have a conflict with other products that install a Mirror Driver.

**\* Windows Vista Aero view:**

A problem existed where Windows Vista Aero would be disabled when LiteShow Manager started, but never re-enabled. This patch restores Vista Aero functionality when LiteShow Manager is not running.

**\* DVD software players using video overlays:**

A problem existed where software based DVD players that use video overlays would generate an error message if LiteShow Manager was installed on the same system. This patch resolves this issue when LiteShow Manager is not running.